

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RELIABLE MUSIC (Continued)

S105764942

Wells Affected: No
Num Affected: Not reported
Wells Contam: Not reported
Sampled By: Y
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: Not reported
Longitude: Not reported
Latitude Number: Not reported
Longitude Number: Not reported
Latitude Decimal: Not reported
Longitude Decimal: Not reported
GPS: 7
Agency: DWM
Facility ID: 27401
Last Modified: 2/21/2003
Incident Phase: Closed Out
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

24
NE
1/4-1/2
0.278 mi.
1469 ft.

STONEWALL STREET SITE
560 E STONEWALL ST
CHARLOTTE, NC 28202

NC LUST S118362135
N/A

Relative:
Lower

LUST:

Actual:
706 ft.

Facility ID: Not reported
UST Number: MO-9031
Incident Number: 40523
Contamination Type: GW
Source Type: Leak-underground
Product Type: P
Date Reported: 09/23/2015
Date Occur: 09/15/2015
Cleanup: 09/15/2015
Closure Request: Not reported
Close Out: 09/23/2015
Level Of Soil Cleanup Achieved: Not reported
Tank Regulated Status: R
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: Not reported
Risk Class Based On Review: Not reported
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STONEWALL STREET SITE (Continued)

S118362135

Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Not reported
MTBE: No
MTBE1: No
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in House
RBCA GW: Not reported
PETOPT: 3
RPL: False
CD Num: 0
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: N
Valid: False
Lat/Long Decimal: 35.2189 -80.8441
Testlat: Not reported
Regional Officer Project Mgr: DPB
Region: MOR
Company: Not reported
Contact Person: Not reported
Telephone: Not reported
RP Address: Not reported
RP City,St,Zip: NC
RP County: Not reported
Comments: Not reported
5 Min Quad: Not reported

PIRF:

Facility Id: 40523
Date Occurred: 2015-09-15 00:00:00
Date Reported: 2015-09-23 00:00:00
Description Of Incident: Not reported
Owner/Operator: Not reported
Ownership: 1
Operation Type: 6
Type: 3
Location: 1
Site Priority: Not reported
Priority Update: Not reported
Wells Affected Y/N: n
Samples Include: Not reported
7#5 Minute Quad: Y
5 Minute Quad: Not reported
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: Not reported
Err Type: 3
Cause: 7
Source: G
Ust Number: P

Last Modified: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

STONEWALL STREET SITE (Continued)

S118362135

Incident Phase: Not reported
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

26
NNW
1/4-1/2
0.278 mi.
1470 ft.

SUMMIT GRANDVIEW DEVELOPMENT
300 BLOCK EAST MOREHEAD ST / S
CHARLOTTE, NC

NC IMD S105703168
N/A

Relative:
Higher

IMD:

Actual:
762 ft.

Region: MOR
Facility ID: 86462
Date Occurred: 12/30/2002
Submit Date: 12/30/2002
GW Contam: Yes, Groundwater Contamination has been detected
Soil Contam: Not reported
Incident Desc: GW SECTION RECD 99 EXCAVATION REPORT FROM UST SECTION 12/02. INFO NOT
CLEAR ON POSSIBLE UST RELEASE. APPARENT SOLVENT RELEASE LIKELY RELATED
TO FMR DRY CLEANER.
Operator: /
Contact Phone: Not reported
Owner Company: Not reported
Operator Address: Not reported
Operator City: Not reported
Oper City,St,Zip: Not reported
Ownership: Not Reported
Operation: Not Reported
Material: Not reported
Qty Lost 1: Not reported
Qty Recovered 1: Not reported
Source: Leak-underground
Type: Other petroleum product
Location: Not reported
Setting: Not reported
Risk Site: Not reported
Site Priority: 0
Priority Code: E
Priority Update: Not reported
Dem Contact: DWM
Wells Affected: No
Num Affected: 0
Wells Contam: Not reported
Sampled By: Not reported
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: 35.219166
Longitude: -80.848888
Latitude Number: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SUMMIT GRANDVIEW DEVELOPMENT (Continued)

S105703168

Longitude Number: Not reported
Latitude Decimal: Not reported
Longitude Decimal: Not reported
GPS: EST
Agency: DWQ
Facility ID: 86462
Last Modified: 12/30/2002
Incident Phase: NOD
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

H26
WNW
1/4-1/2
0.280 mi.
1480 ft.

SIMPSON'S LIGHTING
1200 SOUTH BOULEVARD
CHARLOTTE, NC 28203

NC LUST S118755733
N/A

Site 1 of 2 in cluster H

Relative:
Higher

LUST:

Actual:
763 ft.

Facility ID: 00-0-000
UST Number: MO-5860
Incident Number: 21111
Contamination Type: SL
Source Type: Leak-underground
Product Type: P
Date Reported: 01/24/2000
Date Occur: 12/15/1999
Cleanup: 12/15/1999
Closure Request: 2000-09-25 00:00:00
Close Out: 10/12/2000
Level Of Soil Cleanup Achieved: Soil to Groundwater
Tank Regulated Status: R
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: H
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: 01/25/2000
Site Priority: H
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Industrial/commercial
MTBE: Not reported
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in Archives

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIMPSON'S LIGHTING (Continued)

S118755733

RBCA GW: Not reported
PETOPT: 3
RPL: False
CD Num: 76
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2180 -80.8516
Testlat: Not reported
Regional Officer Project Mgr: AJS
Region: MOR
Company: SIMPSON'S LIGHTING
Contact Person: VERNON SIMPSON
Telephone: 704-376-5463
RP Address: 1112 SOUTH BLVD
RP City,St,Zip: CHARLOTTE, NC 28203
RP County: ME
Comments: ALL SOILS REMOVED. GW NOT CONTAMINATED
5 Min Quad: Not reported

PIRF:

Facility Id: 21111
Date Occurred: 1999-12-15 00:00:00
Date Reported: 2000-01-25 00:00:00
Description Of Incident: 16000 MG/KG TPH(GASOLINE RANGE) DETECTED DURING UST CLOSURE
Owner/Operator: VERNON SIMPSON
Ownership: 4
Operation Type: 6
Type: 3
Location: 1
Site Priority: Not reported
Priority Update: 2000-01-25 00:00:00
Wells Affected Y/N: Not reported
Samples Include: Not reported
7#5 Minute Quad: Not reported
5 Minute Quad: Not reported
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: MIN_SOIL
Err Type: Not reported
Cause: Not reported
Source: Not reported
Ust Number: Not reported

Last Modified: 2000-07-19 00:00:00

Incident Phase: Closed Out

NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIMPSON'S LIGHTING (Continued)

S118755733

Close-out Report:

2000-07-10 00:00:00

H27
WNW
1/4-1/2
0.280 mi.
1480 ft.

SIMPSONS LIGHTING
1112 SOUTH BOULEVARD
CHARLOTTE, NC 28203

NC UST U003138448
NC IMD N/A

Site 2 of 2 in cluster H

Relative:
Higher

UST:

Actual:
763 ft.

Facility Id: 00-0-0000035117
Contact: SIMPSONS LIGHTING
Contact Address1: 1112 SOUTH BOULEVARD
Contact Address2: Not reported
Contact City/State/Zip: CHARLOTTE, NC 28203
FIPS County Desc: Mecklenburg
Latitude: 35.2175
Longitude: -80.8507

Tank Id: 1
Tank Status: Removed
Installed Date: 01/01/1983
Perm Close Date: 11/15/1996
Product Key: 6
Product Name: Heating Oil/Fuel
Tank Capacity: 550
Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: No
Regulated: No
Tank Construction: Single Wall Steel
Piping Construction: Single Wall Steel
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Single Wall Steel
Decode for PCONS_KEY: Single Wall Steel
Decode for PSYS_KEY: Unknown

Tank Id: 2
Tank Status: Removed
Installed Date: 01/01/1983
Perm Close Date: 12/22/1999
Product Key: 3
Product Name: Gasoline, Gas Mix
Tank Capacity: 2000
Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: Yes

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIMPSON'S LIGHTING (Continued)

U003138448

Regulated: Yes
Tank Construction: Single Wall Steel
Piping Construction: Single Wall Steel
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Single Wall Steel
Decode for PCONS_KEY: Single Wall Steel
Decode for PSYS_KEY: Unknown

Tank Id: 3
Tank Status: Removed
Installed Date: 01/01/1964
Perm Close Date: 12/22/1999
Product Key: 1
Product Name: Diesel
Tank Capacity: 2000
Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: No
Regulated: Yes
Tank Construction: Other
Piping Construction: Other
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Other
Decode for PCONS_KEY: other
Decode for PSYS_KEY: Unknown

IMD:

Region: MOR
Facility ID: 21111
Date Occurred: 12/15/1999
Submit Date: 1/25/2000
GW Contam: No Groundwater Contamination detected
Soil Contam: Yes
Incident Desc: 16000 MG/KG TPH(GASOLINE RANGE) DETECTED DURING UST CLOSURE
Operator: VERNON SIMPSON
Contact Phone: 704-376-5463
Owner Company: SIMPSON'S LIGHTING
Operator Address: 1112 SOUTH BLVD
Operator City: CHARLOTTE
Oper City,St,Zip: CHARLOTTE, NC 28203

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SIMPSONS LIGHTING (Continued)

U003138448

Ownership: Private
Operation: Commercial
Material: GASOLINE
Qty Lost 1: Not reported
Qty Recovered 1: UNKNOWN
Source: Leak-underground
Type: Gasoline/diesel
Location: Facility
Setting: Urban
Risk Site: H
Site Priority: Not reported
Priority Code: Not reported
Priority Update: 1/25/2000
Dem Contact: AJS
Wells Affected: Not reported
Num Affected: Not reported
Wells Contam: Not reported
Sampled By: Not reported
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: 35.21805555
Longitude: -80.85166666
Latitude Number: 351305
Longitude Number: 805106
Latitude Decimal: 35.2180555555556
Longitude Decimal: 80.8516666666667
GPS: 7
Agency: DWM
Facility ID: 21111
Last Modified: 7/19/2000
Incident Phase: Closed Out
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: 7/10/2000

28
WNW
1/4-1/2
0.312 mi.
1650 ft.

PARK ELEVATOR LLC
311 ARLINGTON AVENUE
CHARLOTTE, NC 28203

NC LUST S105548408
NC IMD N/A

Relative:
Higher

LUST:
Facility ID: Not reported
UST Number: MO-6474
Incident Number: 24542
Contamination Type: SL
Source Type: Leak-underground
Product Type: P
Date Reported: 08/27/2002

Actual:
738 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARK ELEVATOR LLC (Continued)

S105548408

Date Occur: 07/10/1996
Cleanup: 08/27/2002
Closure Request: Not reported
Close Out: Not reported
Level Of Soil Cleanup Achieved: Not reported
Tank Regulated Status: N
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: Not reported
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Not reported
MTBE: No
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in House
RBCA GW: Not reported
PETOPT: 4
RPL: False
CD Num: 0
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2170 -80.8526
Testlat: Not reported
Regional Officer Project Mgr: BLM
Region: MOR
Company: THE PARK MANUFACTURING CO
Contact Person: KENNETH SUMMEY (PRES)
Telephone: 7048696128
RP Address: PO BOX 12866
RP City,St,Zip: GASTONIA, NC 28052
RP County: Not reported
Comments: 2000-GALLON HEATING OIL UST
5 Min Quad: Not reported

PIRF:

Facility Id: 24542
Date Occurred: 1996-07-10 00:00:00
Date Reported: 2002-08-27 00:00:00
Description Of Incident: SOIL SAMPLES, AROUND FORMER 2K GALLON HEATING OIL UST, INDICATED TPH AS HIGH AS 7600 PPM (3550). UST WAS REPORTEDLY LAST USED ON OR ABOUT 1968.
Owner/Operator: KENNETH SUMMEY (PRES)
Ownership: 4
Operation Type: Not reported
Type: 4

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARK ELEVATOR LLC (Continued)

S105548408

Location: 1
Site Priority: U
Priority Update: 2002-08-28 00:00:00
Wells Affected Y/N: Not reported
Samples Include: Not reported
7#5 Minute Quad: Not reported
5 Minute Quad: Not reported
Pirt/Min Soil: Not reported
Release Code: Not reported
Source Code: Not reported
Err Type: 3
Cause: Not reported
Source: C
Ust Number: C

Last Modified: 2002-08-27 00:00:00

Incident Phase: Response

NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

IMD:

Region: MOR
Facility ID: 24542
Date Occurred: 7/10/1996
Submit Date: 8/27/2002
GW Contam: No Groundwater Contamination detected
Soil Contam: Yes
Incident Desc: SOIL SAMPLES, AROUND FORMER 2K GALLON HEATING OIL UST, INDICATED TPH AS HIGH AS 7600 PPM (3550). UST WAS REPORTEDLY LAST USED ON OR ABOUT 1968.
Operator: KENNETH SUMMEY (PRES)
Contact Phone: 7048696128
Owner Company: THE PARK MANUFACTURING CO
Operator Address: PO BOX 12866
Operator City: GASTONIA
Oper City, St, Zip: GASTONIA, NC 28052
Ownership: Private
Operation: Not reported
Material: Not reported
Qty Lost 1: Not reported
Qty Recovered 1: Not reported
Source: Leak-underground
Type: Gasoline/diesel
Location: Facility
Setting: Not reported
Risk Site: L
Site Priority: U
Priority Code: Not reported
Priority Update: 8/28/2002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

PARK ELEVATOR LLC (Continued)

S105548408

Dem Contact: CBC
Wells Affected: Not reported
Num Affected: Not reported
Wells Contam: Not reported
Sampled By: Not reported
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: Not reported
Longitude: Not reported
Latitude Number: Not reported
Longitude Number: Not reported
Latitude Decimal: Not reported
Longitude Decimal: Not reported
GPS: 7
Agency: DWM
Facility ID: 24542
Last Modified: 8/27/2002
Incident Phase: RE
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

I29
West
1/4-1/2
0.325 mi.
1715 ft.

CHARLOTTE MGP NO. 2
1400 SOUTH BOULEVARD
CHARLOTTE, NC 28203

EDR MGP 1008407278
N/A

Site 1 of 3 in cluster I

Relative:
Higher

Manufactured Gas Plants:

Alternate Name: CHARLOTTE COAL GAS PLANT NO. 2. No additional information available

Actual:
740 ft.

I30
West
1/4-1/2
0.325 mi.
1715 ft.

CHARLOTTE COAL GAS PLANT NO. 2
1400 SOUTH BOULEVARD
CHARLOTTE, NC

NC SHWS S118755452
NC VCP N/A

Site 2 of 3 in cluster I

Relative:
Higher

SHWS:

EPAID: NCD986188803
Lat/Longitude: 35.21573 / -80.85399

Actual:
740 ft.

Geolocation Method: On Screen Placement On Georeferenced Map

VCP:

EPAID: NCD986188803

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

131
West
1/4-1/2
0.335 mi.
1770 ft.

DUKE POWER - S. BLVD.
1412 SOUTH BOULEVARD
CHARLOTTE, NC 28203

NC LUST S105764690
NC IMD N/A

Site 3 of 3 in cluster I

Relative:
Higher

Actual:
743 ft.

LUST:

Facility ID: 00-0-000
UST Number: MO-4380
Incident Number: 14173
Contamination Type: GW
Source Type: Leak-underground
Product Type: P
Date Reported: 06/18/1990
Date Occur: 06/01/1990
Cleanup: 06/01/1990
Closure Request: Not reported
Close Out: Not reported
Level Of Soil Cleanup Achieved: Not reported
Tank Regulated Status: R
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: 060E
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Not reported
MTBE: Not reported
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in House
RBCA GW: Not reported
PETOPT: 3
RPL: False
CD Num: 0
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2160 -80.8539
Testlat: Not reported
Regional Officer Project Mgr: DPB
Region: MOR
Company: DUKE POWER COMPANY
Contact Person: RALPH ROBERTS
Telephone: Not reported
RP Address: PO BOX 1007
RP City,St,Zip: CHARLOTTE, NC 28201
RP County: ME
Comments: SUPERFUND SECTION TOOK OVER WHOLE SITE 11/4/2004

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DUKE POWER - S. BLVD. (Continued)

S105764690

5 Min Quad: Not reported

PIRF:

Facility Id: 14173
Date Occurred: 1994-08-25 00:00:00
Date Reported: 1995-06-27 00:00:00
Description Of Incident: UPON REMOVAL OF 3 USTS, SOIL CONTAM. WAS CONFIRMED.
Owner/Operator: MR. RALPH ROBERTS
Ownership: 4
Operation Type: 6
Type: 3
Location: 1
Site Priority: 060E
Priority Update: 1998-05-15 00:00:00
Wells Affected Y/N: Not reported
Samples Include: 0
7#5 Minute Quad: Not reported
5 Minute Quad: Not reported
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: Pirf
Err Type: Not reported
Cause: Not reported
Source: Not reported
Ust Number: Not reported

Last Modified: Not reported

Incident Phase: Response

NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

IMD:

Region: MOR
Facility ID: 14173
Date Occurred: 6/1/1990
Submit Date: 6/27/1995
GW Contam: Yes, Groundwater Contamination has been detected
Soil Contam: No
Incident Desc: UPON REMOVAL OF 3 USTS, SOIL CONTAM. WAS CONFIRMED.
Operator: MR. RALPH ROBERTS
Contact Phone: Not reported
Owner Company: DUKE POWER COMPANY
Operator Address: PO BOX 1007
Operator City: CHARLOTTE
Oper City,St,Zip: CHARLOTTE, NC 28201
Ownership: Private
Operation: Commercial
Material: GASOLINE
Qty Lost 1: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DUKE POWER - S. BLVD. (Continued)

S105764690

Qty Recovered 1: Not reported
Source: Leak-underground
Type: Gasoline/diesel
Location: Facility
Setting: Residential
Risk Site: L
Site Priority: 060E
Priority Code: L
Priority Update: 5/15/1998
Dem Contact: CER
Wells Affected: Not reported
Num Affected: 0
Wells Contam: Not reported
Sampled By: Not reported
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: Not reported
Longitude: Not reported
Latitude Number: Not reported
Longitude Number: Not reported
Latitude Decimal: Not reported
Longitude Decimal: Not reported
GPS: NOD
Agency: DWM
Facility ID: 14173
Last Modified: Not reported
Incident Phase: RE
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

J32 SCOTT CARS, INC.(ARNOLD PALMER
NNE 501 S. CALDWELL ST
1/4-1/2 CHARLOTTE, NC
0.338 mi.
1785 ft. Site 1 of 3 in cluster J

NC IMD S103717119
N/A

Relative:
Higher

IMD:

Actual:
738 ft.

Region: MOR
Facility ID: 18814
Date Occurred: Not reported
Submit Date: 7/24/1998
GW Contam: Yes, Groundwater Contamination has been detected
Soil Contam: No
Incident Desc: GW CONTAM. WAS FOUND FOR HEAVY OIL, TPH, CHROMIUM, AND LEAD.
Operator: Not reported
Contact Phone: Not reported
Owner Company: SCOTT CARS, INC.
Operator Address: 400 TYVOLA ROAD

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCOTT CARS, INC.(ARNOLD PALMER (Continued)

S103717119

Operator City: CHARLOTTE
Oper City,St,Zip: CHARLOTTE, NC 28217
Ownership: Private
Operation: Commercial
Material: HYDRAULIC OIL
Qty Lost 1: Not reported
Qty Recovered 1: Not reported
Material: WASTE OIL
Qty Lost: Not reported
Qty Recovered: Not reported
Material: VIRGIN OIL
Qty Lost: Not reported
Qty Recovered 3: Not reported
Source: Leak-underground
Type: Gasoline/diesel
Location: Facility
Setting: Industrial
Risk Site: L
Site Priority: E
Priority Code: E
Priority Update: 7/24/1998
Dem Contact: CSF
Wells Affected: No
Num Affected: Not reported
Wells Contam: Not reported
Sampled By: Responsible Parties
Samples Include: Groundwater Samples
7.5 Min Quad: Not reported
5 Min Quad: R66J
Latitude: 35.22027777
Longitude: -80.84361111
Latitude Number: 351313
Longitude Number: 805037
Latitude Decimal: 35.2202777777778
Longitude Decimal: 80.8436111111111
GPS: NOD
Agency: DWM
Facility ID: 18814
Last Modified: Not reported
Incident Phase: RE
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

J33
NNE
1/4-1/2
0.338 mi.
1785 ft.

ARNOLD PALMER CADILLAC
501 SOUTH CALDWELL STREET
CHARLOTTE, NC 28202

Site 2 of 3 in cluster J

NC LUST
NC UST

U003562570
N/A

Relative:
Higher

Actual:
738 ft.

LUST:

Facility ID: 00-0-000
UST Number: MO-5416
Incident Number: 18814
Contamination Type: GW
Source Type: Leak-underground
Product Type: P
Date Reported: 04/02/1998
Date Occur: Not reported
Cleanup: 04/02/1998
Closure Request: Not reported
Close Out: Not reported
Level Of Soil Cleanup Achieved: Industrial/Commercial
Tank Regulated Status: R
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: E
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Not reported
MTBE: Not reported
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in House
RBCA GW: Not reported
PETOPT: 5
RPL: False
CD Num: 0
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2202 -80.8436
Testlat: Not reported
Regional Officer Project Mgr: DPB
Region: MOR
Company: SCOTT CARS, INC.
Contact Person: Not reported
Telephone: Not reported
RP Address: 400 TYVOLA ROAD
RP City,St,Zip: CHARLOTTE, NC 28217
RP County: ME
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARNOLD PALMER CADILLAC (Continued)

U003562570

5 Min Quad: Not reported

PIRF:

Facility Id: 18814
Date Occurred: 1998-07-19 00:00:00
Date Reported: 1998-07-24 00:00:00
Description Of Incident: GW CONTAM. WAS FOUND FOR HEAVY OIL, TPH, CHROMIUM, AND LEAD.
Owner/Operator: Not reported
Ownership: 4
Operation Type: 6
Type: 5
Location: 1
Site Priority: E
Priority Update: 1998-07-24 00:00:00
Wells Affected Y/N: N
Samples Include: Not reported
7#5 Minute Quad: 3
5 Minute Quad: 1
Pirf/Min Soil: Not reported
Release Code: R86J
Source Code: Pirf
Err Type: Not reported
Cause: Not reported
Source: Not reported
Ust Number: Not reported

Last Modified: Not reported

Incident Phase: Response

NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

Facility ID: Not reported
UST Number: MO-2062
Incident Number: 27097
Contamination Type: SL
Source Type: Leak-underground
Product Type: P
Date Reported: 05/27/1994
Date Occur: 07/21/1993
Cleanup: 07/21/1993
Closure Request: Not reported
Close Out: 07/06/1994
Level Of Soil Cleanup Achieved: Not reported
Tank Regulated Status: R
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARNOLD PALMER CADILLAC (Continued)

U003562570

NORR Issue Date: Not reported
Site Priority: Not reported
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Not reported
MTBE: Not reported
MTBE1: Unknown
Flag: Yes
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in Archives
RBCA GW: Not reported
PETOPT: 3
RPL: False
CD Num: 11
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2198 -80.8434
Testlat: Not reported
Regional Officer Project Mgr: MT
Region: MOR
Company: Not reported
Contact Person: Not reported
Telephone: Not reported
RP Address: Not reported
RP City,St,Zip: Not reported
RP County: Not reported
Comments: Not reported
5 Min Quad: Not reported

PIRF:
Facility Id: 27097
Date Occurred: 1993-07-21 00:00:00
Date Reported: 1994-05-27 00:00:00
Description Of Incident: 4.5 TPH AT TIME OF CLOSURE; SITE IS CLOSED
Owner/Operator: Not reported
Ownership: 4
Operation Type: 6
Type: 3
Location: 1
Site Priority: Not reported
Priority Update: Not reported
Wells Affected Y/N: N
Samples Include: Not reported
7#5 Minute Quad: Y
5 Minute Quad: S
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: Not reported
Err Type: 2
Cause: Not reported
Source: C
Ust Number: C

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARNOLD PALMER CADILLAC (Continued)

U003562570

Last Modified: Not reported
Incident Phase: Not reported
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

UST:

Facility Id: 00-0-0000014226
Contact: PACE OIL COMPANY INC
Contact Address1: PO BOX 15047 150 STRATFORD CT SW
Contact Address2: Not reported
Contact City/State/Zip: WINSTON SALEM, NC 27103-0047
FIPS County Desc: Mecklenburg
Latitude: 0
Longitude: 0

Tank Id: 1
Tank Status: Removed
Installed Date: 06/29/1977
Perm Close Date: 07/31/1992
Product Key: 3
Product Name: Gasoline, Gas Mix
Tank Capacity: 8000
Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: Yes
Regulated: Yes
Tank Construction: Single Wall Steel
Piping Construction: Single Wall Steel
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Single Wall Steel
Decode for PCONS_KEY: Single Wall Steel
Decode for PSYS_KEY: Unknown

Tank Id: 2
Tank Status: Removed
Installed Date: 06/29/1977
Perm Close Date: 07/31/1992
Product Key: 3
Product Name: Gasoline, Gas Mix

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARNOLD PALMER CADILLAC (Continued)

U003562570

Tank Capacity: 8000
Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: Yes
Regulated: Yes
Tank Construction: Single Wall Steel
Piping Construction: Single Wall Steel
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Single Wall Steel
Decode for PCONS_KEY: Single Wall Steel
Decode for PSYS_KEY: Unknown

Tank Id: 3
Tank Status: Removed
Installed Date: 01/01/1964
Perm Close Date: 12/31/1983
Product Key: 20
Product Name: Unknown
Tank Capacity: 500
Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: No
Regulated: Yes
Tank Construction: Other
Piping Construction: Unknown
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Other
Decode for PCONS_KEY: Unknown
Decode for PSYS_KEY: Unknown

Tank Id: 4
Tank Status: Removed
Installed Date: 01/01/1964
Perm Close Date: 12/31/1983
Product Key: 20
Product Name: Unknown
Tank Capacity: 500

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARNOLD PALMER CADILLAC (Continued)

U003562570

Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: No
Regulated: Yes
Tank Construction: Unknown
Piping Construction: Unknown
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Unknown
Decode for PCONS_KEY: Unknown
Decode for PSYS_KEY: Unknown

Tank Id: 5
Tank Status: Removed
Installed Date: 01/01/1964
Perm Close Date: 12/31/1983
Product Key: 20
Product Name: Unknown
Tank Capacity: 1000
Root Tank Id: Not reported
Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: No
Regulated: Yes
Tank Construction: Unknown
Piping Construction: Unknown
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Unknown
Decode for PCONS_KEY: Unknown
Decode for PSYS_KEY: Unknown

Tank Id: 6
Tank Status: Removed
Installed Date: 01/01/1964
Perm Close Date: 12/31/1983
Product Key: 20
Product Name: Unknown
Tank Capacity: 500
Root Tank Id: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

ARNOLD PALMER CADILLAC (Continued)

U003562570

Main Tank: No
Compartment Tank: No
Manifold Tank: Not reported
Commercial: No
Regulated: Yes
Tank Construction: Unknown
Piping Construction: Unknown
Piping System Key: Unknown
Other CP Tank: Not reported
Overfill Protection Key: 1
Overfill Protection Name: Unknown
Spill Protection Key: 1
Spill Protection Name: Unknown
Leak Detection Key: -1
Leak Detection Name: Unknown
Decode for TCONS_KEY: Unknown
Decode for PCONS_KEY: Unknown
Decode for PSYS_KEY: Unknown

J34
NNE
1/4-1/2
0.338 mi.
1785 ft.

SCOTT BUICK
501 SOUTH CALDWELL
CHARLOTTE, NC

NC IMD S105702889
N/A

Site 3 of 3 in cluster J

Relative:
Higher

IMD:

Actual:
738 ft.

Region: MOR
Facility ID: 27097
Date Occurred: 7/21/1993
Submit Date: 5/27/1994
GW Contam: No Groundwater Contamination detected
Soil Contam: Yes
Incident Desc: 4.5 TPH AT TIME OF CLOSURE; SITE IS CLOSED
Operator: Not reported
Contact Phone: Not reported
Owner Company: Not reported
Operator Address: Not reported
Operator City: Not reported
Oper City, St, Zip: Not reported
Ownership: Private
Operation: Commercial
Material: GASOLINE
Qty Lost 1: UNKOWN
Qty Recovered 1: NONE
Source: Leak-underground
Type: Gasoline/diesel
Location: Facility
Settling: Not reported
Risk Site: Not reported
Site Priority: Not reported
Priority Code: Not reported
Priority Update: Not reported
Dem Contact: MT
Wells Affected: No
Num Affected: Not reported
Wells Contam: Not reported
Sampled By: Y
Samples Include: S

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SCOTT BUICK (Continued)

S105702889

7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: Not reported
Longitude: Not reported
Latitude Number: Not reported
Longitude Number: Not reported
Latitude Decimal: Not reported
Longitude Decimal: Not reported
GPS: 7
Agency: DWM
Facility ID: Not reported
Last Modified: Not reported
Incident Phase: Not reported
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

35
NNE
1/4-1/2
0.344 mi.
1815 ft.

CHARLOTTE CONVENTION CENTER
STONEWALL & BREVARD
CHARLOTTE, NC

NC LUST TRUST S105218579
N/A

Relative:
Lower

LUST TRUST:

Facility ID: Not reported
Site ID: 10374
Site Note: Not reported
Site Eligible?: True
Commercial Find: 100% Commercial
Priority Rank: Low
Deductable Amount: 50000
3rd Party Deductable Amt: 0
Sum 3rd Party Amt Applied: 0

Actual:
718 ft.

36
SSW
1/4-1/2
0.354 mi.
1869 ft.

KRISTEN HENDERSON RESIDENCE
720 BERKELEY AVENUE
CHARLOTTE, NC 28203

NC LUST S101714921
NC IMD N/A

Relative:
Higher

LUST:

Facility ID: Not reported
UST Number: MO-4483
Incident Number: 14760
Contamination Type: SL
Source Type: Leak-underground
Product Type: P
Date Reported: 11/14/1995

Actual:
750 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KRISTEN HENDERSON RESIDENCE (Continued)

S101714921

Date Occur: 08/28/1995
Cleanup: 08/28/1995
Closure Request: Not reported
Close Out: 08/12/2003
Level Of Soil Cleanup Achieved: Not reported
Tank Regulated Status: N
Of Supply Wells: 0
Commercial/NonCommercial UST Site: NON COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: E
Phase Of LSA Req: 1
Site Risk Reason: Not reported
Land Use: Not reported
MTBE: Not reported
MTBE1: Unknown
Flag: Yes
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in Archives
RBCA GW: Not reported
PETOPT: 4
RPL: False
CD Num: 184
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2104 -80.8495
Testlat: Not reported
Regional Officer Project Mgr: STF
Region: MOR
Company: UNKNOWN
Contact Person: UNKNOWN-NOT CURRENT RESIDENT
Telephone: Not reported
RP Address: UNKNOWN
RP City,St,Zip: UNKNOWN, UN
RP County: UNKNOWN
Comments: CLOSED BY STATE LEAD
5 Min Quad: Not reported

PIRF:

Facility Id: 14760
Date Occurred: 1995-08-28 00:00:00
Date Reported: 1995-11-14 00:00:00
Description Of Incident: DURING HEAVY RAINS A UST UNKNOWN TO PROPERTY OWNER OVERFLOWED.
Owner/Operator: UNKNOWN-NOT CURRENT RESIDENT
Ownership: 3
Operation Type: Not reported
Type: 4
Location: 7
Site Priority: E

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KRISTEN HENDERSON RESIDENCE (Continued)

S101714921

Priority Update: 1998-05-30 00:00:00
Wells Affected Y/N: N
Samples Include: 0
7#5 Minute Quad: Not reported
5 Minute Quad: Not reported
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: Pirf
Err Type: Not reported
Cause: Not reported
Source: Not reported
Ust Number: Not reported

Last Modified: Not reported
Incident Phase: Closed Out
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

IMD:

Region: MOR
Facility ID: 14760
Date Occurred: 8/28/1995
Submit Date: 11/14/1995
GW Contam: No Groundwater Contamination detected
Soil Contam: Yes
Incident Desc: DURING HEAVY RAINS A UST UNKNOWN TO PROPERTY OWNER OVERFLOWED.
Operator: UNKNOWN-NOT CURRENT RESIDENT
Contact Phone: Not reported
Owner Company: UNKNOWN
Operator Address: UNKNOWN
Operator City: UNKNOWN
Oper City, St, Zip: UNKNOWN, UN
Ownership: Unknown
Operation: Not reported
Material: HEATING OIL
Qty Lost 1: Not reported
Qty Recovered 1: Not reported
Source: Leak-underground
Type: Gasoline/diesel
Location: Residence
Setting: Residential
Risk Site: L
Site Priority: E
Priority Code: L
Priority Update: 5/30/1998
Dem Contact: STF
Wells Affected: No
Num Affected: 0
Wells Contam: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

KRISTEN HENDERSON RESIDENCE (Continued)

S101714921

Sampled By: Not reported
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: 35.2105
Longitude: -80.8494
Latitude Number: Not reported
Longitude Number: Not reported
Latitude Decimal: Not reported
Longitude Decimal: Not reported
GPS: NOD
Agency: DWM
Facility ID: 14760
Last Modified: Not reported
Incident Phase: Closed Out
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

37 DUKE POWER - SOUTH BLVD
West 222 EAST BLAND STREET
1/4-1/2 CHARLOTTE, NC 28203
0.374 mi.
1974 ft.

NC LUST S105764443
NC IMD N/A

Relative: LUST:
Higher Facility ID: Not reported
UST Number: MO-2835
Actual: Incident Number: 3836
765 ft. Contamination Type: GW
Source Type: Leak-underground
Product Type: P
Date Reported: 12/06/1988
Date Occur: Not reported
Cleanup: 12/06/1988
Closure Request: Not reported
Close Out: Not reported
Level Of Soil Cleanup Achieved: Not reported
Tank Regulated Status: R
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: L
Risk Class Based On Review: I
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: 070E
Phase Of LSA Req: Not reported
Site Risk Reason: Gross contaminant levels
Land Use: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DUKE POWER - SOUTH BLVD (Continued)

S105764443

MTBE: Not reported
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in House
RBCA GW: Not reported
PETOPT: 3
RPL: False
CD Num: 0
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2159 -80.8541
Testlat: Not reported
Regional Officer Project Mgr: DPB
Region: MOR
Company: DUKE POWER COMPANY
Contact Person: D.E.M.SULLIVAN
Telephone: 704-373-7894
RP Address: PO BOX 33189
RP City,St,Zip: CHARLOTTE, NC 28242
RP County: ME
Comments: GW OVER GCLS (old Coor 35.1253 80.5119)
5 Min Quad: Not reported

PIRF:

Facility Id: 3836
Date Occurred: 1988-10-18 00:00:00
Date Reported: 1988-12-07 00:00:00
Description Of Incident: ROUTINE TESTING OF UNLEADED GASOLINE UST SHOWED A LEAK IN THE PIPING.
Owner/Operator: MR.D.E.M.SULLIVAN
Ownership: 4
Operation Type: 6
Type: 3
Location: 1
Site Priority: 070E
Priority Update: 1998-05-15 00:00:00
Wells Affected Y/N: N
Samples Include: 0
7#5 Minute Quad: 4
5 Minute Quad: Not reported
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: Pirf
Err Type: Not reported
Cause: Not reported
Source: Not reported
Ust Number: Not reported

Last Modified: Not reported
Incident Phase: Not reported
NOV Issued: Not reported
NORR Issued: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DUKE POWER - SOUTH BLVD (Continued)

S105764443

45 Day Report:	Not reported
Public Meeting Held:	Not reported
Corrective Action Planned:	Not reported
SOC Signed:	Not reported
Reclassification Report:	Not reported
RS Designation:	Not reported
Closure Request Date:	Not reported
Close-out Report:	Not reported

IMD:

Region: MOR
Facility ID: 3836
Date Occurred: Not reported
Submit Date: 12/7/1988
GW Contam: Yes, Groundwater Contamination has been detected
Soil Contam: No
Incident Desc: ROUTINE TESTING OF UNLEADED GASOLINE UST SHOWED A LEAK IN THE PIPING.
Operator: MR.D.E.M.SULLIVAN
Contact Phone: 704-373-7894
Owner Company: DUKE POWER COMPANY
Operator Address: PO BOX 33189
Operator City: CHARLOTTE
Oper City, St, Zip: CHARLOTTE, NC 28242
Ownership: Private
Operation: Commercial
Material: UNL. GASOLINE
Qty Lost 1: Not reported
Qty Recovered 1: NONE
Source: Leak-underground
Type: Gasoline/diesel
Location: Facility
Setting: Industrial
Risk Site: L
Site Priority: 070E
Priority Code: L
Priority Update: 5/15/1998
Dem Contact: AJS
Wells Affected: No
Num Affected: 0
Wells Contam: Not reported
Sampled By: Other
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: 35.21472222
Longitude: -80.85527777
Latitude Number: 351253
Longitude Number: 805119
Latitude Decimal: 35.214722222222
Longitude Decimal: 80.855277777778
GPS: NOD
Agency: DWM
Facility ID: 3836
Last Modified: Not reported
Incident Phase: Not reported
NOV Issued: Not reported
NORR Issued: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DUKE POWER - SOUTH BLVD (Continued)

S105764443

45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

38
South
1/4-1/2
0.404 mi.
2131 ft.

IVEY RESIDENCE - MARK
1315 LEXINGTON AVENUE
CHARLOTTE, NC 28203

NC LUST S112061326
NC LUST TRUST N/A

Relative:
Lower

LUST:

Actual:
719 ft.

Facility ID: Not reported
UST Number: MO-8546
Incident Number: 40085
Contamination Type: SL
Source Type: Leak-underground
Product Type: P
Date Reported: 07/02/2012
Date Occur: 06/14/2012
Cleanup: 06/14/2012
Closure Request: Not reported
Close Out: 07/17/2012
Level Of Soil Cleanup Achieved: Soil to Groundwater
Tank Regulated Status: N
Of Supply Wells: 0
Commercial/NonCommercial UST Site: NON COMMERCIAL
Risk Classification: U
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: Not reported
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Residential
MTBE: No
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located in Archives
RBCA GW: Not reported
PETOPT: 4
RPL: False
CD Num: 550
Reel Num: 0
RPOW: True
RPOP: False
Error Flag: 0
Error Code: N
Valid: False

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IVEY RESIDENCE - MARK (Continued)

S112061326

Lat/Long Decimal: 35.2094 -80.8455
Testlat: Not reported
Regional Officer Project Mgr: BLM
Region: MOR
Company: Not reported
Contact Person: MARK IVEY
Telephone: Not reported
RP Address: Not reported
RP City,St,Zip: NC
RP County: Not reported
Comments: Not reported
5 Min Quad: Not reported

PIRF:

Facility Id: 40085
Date Occurred: 2012-06-14 00:00:00
Date Reported: 2012-07-02 00:00:00
Description Of Incident: Not reported
Owner/Operator: Not reported
Ownership: 4
Operation Type: 3
Type: 4
Location: 7
Site Priority: Not reported
Priority Update: Not reported
Wells Affected Y/N: N
Samples Include: Not reported
7#5 Minute Quad: Y
5 Minute Quad: Not reported
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: Not reported
Err Type: 2
Cause: 7
Source: G
Ust Number: P

Last Modified: Not reported
Incident Phase: Not reported
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

LUST TRUST:

Facility ID: Not reported
Site ID: 40085
Site Note: Noncommercial; 100% eligible; \$0 deductible. Track this as a site that would have been 5K + 10% as this is receiving 100% because of Session Law 2010-154. [CGS 7/2/13]
Site Eligible?: True

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

IVEY RESIDENCE - MARK (Continued)

S112061326

Commercial Find: 100% Non-Commercial
Priority Rank: Not reported
Deductable Amount: 0
3rd Party Deductable Amt: 0
Sum 3rd Party Amt Applied: 0

K39
WNW
1/4-1/2
0.407 mi.
2151 ft.

SOUTH END SQUARE
1235 SOUTH TRYON STREET
CHARLOTTE, NC 28203

NC LUST S105120323
NC IMD N/A

Site 1 of 3 in cluster K

Relative:
Higher

Actual:
772 ft.

LUST:
Facility ID: Not reported
UST Number: MO-6157
Incident Number: 23335
Contamination Type: GW
Source Type: Leak-underground
Product Type: P
Date Reported: 06/22/2001
Date Occur: 05/17/2001
Cleanup: 05/17/2001
Closure Request: Not reported
Close Out: 10/05/2001
Level Of Soil Cleanup Achieved: Residential
Tank Regulated Status: R
Of Supply Wells: 0
Commercial/NonCommercial UST Site: COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: Not reported
Phase Of LSA Req: 2
Site Risk Reason: Not reported
Land Use: Residential
MTBE: No
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: 10/09/2001
Release Detection: 0
Current Status: File Located in Archives
RBCA GW: Cleanups to alternate standards
PETOPT: 3
RPL: False
CD Num: 78
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: Not reported
Valid: False
Lat/Long Decimal: 35.2183 -80.8536
Testlat: Not reported
Regional Officer Project Mgr: AJS
Region: MOR

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SOUTH END SQUARE (Continued)

S105120323

Company: UNKNOWN
Contact Person: Not reported
Telephone: Not reported
RP Address: Not reported
RP City,St,Zip: NC
RP County: Not reported
Comments: Not reported
5 Min Quad: Not reported

PIRF:

Facility Id: 23335
Date Occurred: 2001-05-17 00:00:00
Date Reported: 2001-07-10 00:00:00
Description Of Incident: GROUNDWATER AND SOIL CONTAMINATION DISCOVERED DURING UST INVESTIGATION
Owner/Operator: PAUL JOHNSTON / FF REALTY, LLC
Ownership: 4
Operation Type: Not reported
Type: 3
Location: 8
Site Priority: L
Priority Update: 2001-10-02 00:00:00
Wells Affected Y/N: N
Samples Include: Not reported
7#5 Minute Quad: Not reported
5 Minute Quad: Not reported
Pirf/Min Soil: Not reported
Release Code: Not reported
Source Code: Not reported
Err Type: 3
Cause: Not reported
Source: Not reported
Ust Number: Not reported

Last Modified: 2001-12-06 00:00:00

Incident Phase: **Closed Out**

NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: 2001-09-27 00:00:00

IMD:

Region: MOR
Facility ID: 23335
Date Occurred: 5/17/2001
Submit Date: 7/10/2001
GW Contam: Yes, Groundwater Contamination has been detected
Soil Contam: No
Incident Desc: GROUNDWATER AND SOIL CONTAMINATION DISCOVERED DURING UST INVESTIGATION
Operator: Not reported
Contact Phone: Not reported
Owner Company: UNKNOWN

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

SOUTH END SQUARE (Continued)

S105120323

Operator Address: Not reported
Operator City: Not reported
Oper City, St, Zip: NC
Ownership: Private
Operation: Not reported
Material: Not reported
Qty Lost 1: Not reported
Qty Recovered 1: Not reported
Source: Leak-underground
Type: Gasoline/diesel
Location: 8
Setting: Urban
Risk Site: L
Site Priority: L
Priority Code: L
Priority Update: 10/2/2001
Dem Contact: AJS
Wells Affected: No
Num Affected: Not reported
Wells Contam: Not reported
Sampled By: Not reported
Samples Include: Not reported
7.5 Min Quad: Not reported
5 Min Quad: Not reported
Latitude: 35.2175
Longitude: -80.85444444
Latitude Number: 351303
Longitude Number: 805116
Latitude Decimal: 35.2175
Longitude Decimal: 80.854444444444
GPS: 7
Agency: DWM
Facility ID: 23335
Last Modified: 12/6/2001
Incident Phase: Closed Out
NOV Issued: Not reported
NORR Issued: Not reported
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: 9/27/2001

K40 **CARROLL ALIGNING SERVICE CO.**
WNW **1305 SOUTH TRYON STREET**
1/4-1/2 **CHARLOTTE, NC 28203**
0.417 mi.
2204 ft. **Site 2 of 3 in cluster K**

NC LUST **S108231236**
NC LUST TRUST **N/A**

Relative: **LUST:**
Higher **Facility ID:** **Not reported**
Actual: **UST Number:** **MO-7536**
764 ft. **Incident Number:** **36175**
Contamination Type: **GW**

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CARROLL ALIGNING SERVICE CO. (Continued)

S108231236

Source Type: Leak-underground
Product Type: P
Date Reported: 10/23/2006
Date Occur: 10/23/2006
Cleanup: 10/23/2006
Closure Request: Not reported
Close Out: 01/29/2007
Level Of Soil Cleanup Achieved: Residential
Tank Regulated Status: N
Of Supply Wells: 0
Commercial/NonCommercial UST Site: NON COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: Not reported
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Industrial/commercial
MTBE: No
MTBE1: No
Flag: No
Flag1: No
LUR Filed: 01/30/2007
Release Detection: 0
Current Status: File Located in Archives
RBCA GW: Cleanups to alternate standards
PETOPT: 4
RPL: False
CD Num: 320
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: N
Valid: False
Lat/Long Decimal: 35.2180 -80.8529
Testlat: Not reported
Regional Officer Project Mgr: AJS
Region: MOR
Company: Not reported
Contact Person: Not reported
Telephone: Not reported
RP Address: Not reported
RP City,St,Zip: NC
RP County: Not reported
Comments: Not reported
5 Min Quad: Not reported
PIRF:
Facility Id: 36175
Date Occurred: 2006-10-23 00:00:00
Date Reported: 2006-10-23 00:00:00
Description Of Incident: Not reported
Owner/Operator: Not reported
Ownership: 4
Operation Type: 6

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CARROLL ALIGNING SERVICE CO. (Continued)

S108231236

Type: 4
Location: 1
Site Priority: Not reported
Priority Update: Not reported
Wells Affected Y/N: N
Samples Include: Not reported
7#5 Minute Quad: Y
5 Minute Quad: Not reported
Plrf/Min Soil: Not reported
Release Code: Not reported
Source Code: Not reported
Err Type: 2
Cause: Not reported
Source: Not reported
Ust Number: P

Last Modified: Not reported
Incident Phase: Closed Out
NOV Issued: Not reported
NORR Issued: 2006-11-30 00:00:00
45 Day Report: Not reported
Public Meeting Held: Not reported
Corrective Action Planned: Not reported
SOC Signed: Not reported
Reclassification Report: Not reported
RS Designation: Not reported
Closure Request Date: Not reported
Close-out Report: Not reported

LUST TRUST:

Facility ID: Not reported
Site ID: 36175
Site Note: Noncommercial; 100% eligible; \$0 deductible.[CGS 4/21/08]
Site Eligible?: True
Commercial Find: 100% Non-Commercial
Priority Rank: Not reported
Deductable Amount: 0
3rd Party Deductable Amt: 0
Sum 3rd Party Amt Applied: 0

L41
South
1/4-1/2
0.420 mi.
2217 ft.

WATSON RESIDENCE
926 BERKELEY AVENUE
CHARLOTTE, NC 28203

Site 1 of 2 in cluster L

NC LUST S118128442
NC LUST TRUST N/A

Relative:
Higher

LUST:

Actual:
735 ft.

Facility ID: Not reported
UST Number: MO-9001
Incident Number: 40494
Contamination Type: SL
Source Type: Leak-underground
Product Type: P
Date Reported: 05/28/2015
Date Occur: 05/27/2015
Cleanup: 05/27/2015
Closure Request: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WATSON RESIDENCE (Continued)

S118128442

Close Out: 06/18/2015
Level Of Soil Cleanup Achieved: Soil to Groundwater
Tank Regulated Status: N
Of Supply Wells: 0
Commercial/NonCommercial UST Site: NON COMMERCIAL
Risk Classification: L
Risk Class Based On Review: L
Corrective Action Plan Type: Not reported
NOV Issue Date: Not reported
NORR Issue Date: Not reported
Site Priority: Not reported
Phase Of LSA Req: Not reported
Site Risk Reason: Not reported
Land Use: Residential
MTBE: No
MTBE1: Unknown
Flag: No
Flag1: No
LUR Filed: Not reported
Release Detection: 0
Current Status: File Located In House
RBCA GW: Not reported
PETOPT: 4
RPL: False
CD Num: 0
Reel Num: 0
RPOW: False
RPOP: False
Error Flag: 0
Error Code: N
Valid: False
Lat/Long Decimal: 35.2089 -80.8469
Testlat: Not reported
Regional Officer Project Mgr: BLM
Region: MOR
Company: Not reported
Contact Person: Not reported
Telephone: Not reported
RP Address: Not reported
RP City,St,Zip: NC
RP County: Not reported
Comments: Not reported
5 Min Quad: Not reported

PIRF:

Facility Id: 40494
Date Occurred: 2015-05-27 00:00:00
Date Reported: 2015-05-28 00:00:00
Description Of Incident: Not reported
Owner/Operator: Not reported
Ownership: 4
Operation Type: 3
Type: 4
Location: 7
Site Priority: Not reported
Priority Update: Not reported
Wells Affected Y/N: N
Samples Include: Not reported